

## **SAS Superstructure**

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

## Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 741 Const Calendar Day: 238 Date: 28-Jan-2013 Monday

Inspector Name: Daouk, Sami Title:

Inspection Type: Continuous

Shift Hours: 07:00 am 03:30 pm Break: 00:30 Over Time:

Federal ID: Location:

Reviewer: Awal, Mohammad Approved Date: 16-Sep-13 Status: Approved

Weather

Temperature 7 AM 12 PM 4PM Precipitation Condition

Diary:

## **Tower Activities**

ABF crews came to the site after the safety meeting at 7:20 AM. Crews had to work on the Electro Slag Weld repairs & work on the top of the tower . They started at 7:30 AM.

Certified Coating crews came to the site at 7:15 AM. Crews had to work on the tower head & diaphragm at 158 meters . They started at 7:20 AM.

James , Eric , Chris , & Reggie had to work on the Electro Slag Weld repairs between 9 & 13 meters .

James had to work on joint F, Face A. He had to clean grind & weld

Eric had to work on joint T, Face B. He had to excavate, grind, clean & weld

Chris had to work on joint M, Face B. He had to clean, grind, & weld.

Reggie had to work with all crews & with the QA & QC . He had to clean & grind in various locations .

William & Steve had to cover all the welding activities . Check William report for the weld repairs detailed activities

Fritz, Robert, Andrew, & Tony were on the site. They had to MT, UT, & Map the repair locations.

Richard , James , & Mathew had to work on dehumidifier brackets . Crews had to weld the brackets on the top of the saddle cover on the East side . They had to prepare their tools , equipments , reroute the gas & power lines . They were done at 8:00 AM. Richard started to weld at 8:05 AM. He was done on the East side at 11:00 AM. He had to weld 7 brackets .

After that , he had to weld the brackets on the West side of the saddle . He started at 10:30 AM. He was done at 2:30 PM.

In addition to that , crews had to closure plates for the orgami plates on the East side chimneys . Crews had to modify the plates . They had to lay out the holes , cut the excess of the plates , smooth the edges , & prepare to weld the plates , & install the bolts .

Certified Coating crews had to work on the tower heads . They had to clean , grind & smooth the top of the diaphragm at 158 meters . Charlie had to cover their activities in the morning & Jeffery had to cover their activities in the afternoon .

Check Charlie & Jeffery 's report for the painters activities



Page 1 of 2

Run date 21-Nov-14

Time

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

6:25 PM

## Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name: Daouk, Sami Diary #: 741 Date: 28-Jan-2013 Monday

Anthony , Augie , Casey , Robert , & Ryan had to work on the East side of the tower . Crews had to prepare the remove the catwalk frames . They started at 8:00 AM. No major work was performed on the removal of the frames .

Mohammad to cover the tower activities after 3:00 PM.

04-0120F4	Bid Item: 053	T-L01-SPD.053	Tower Lift 0	1 Shear	r Plates	and Dia	aphrams	
MERICAN BR	IDGE/FLUOR, A JV							
Labor								
Trade	Class	Name	RT Hrs C	T Hrs I	DT Hrs	Total	Remarks	Dispute
Contractor:	AMERICAN BRIDGE/F	LUOR, A JV						
Ironworker	JNM	JAMES WILKERSON	8.00	2.00	0.00	10.00		
Ironworker	JNM	RICHARD CHOUINARD	0.00	0.00	0.00	0.00		
Ironworker	APP	MATHEW MULLINS	8.00	2.00	0.00	10.00		
Welder	APP	Reggie Humphry	8.00	2.00	0.00	10.00		
Ironworker	FOR	JAMES ZHEN	8.00	2.00	0.00	10.00		
Ironworker	FOR	ERIC SPARKS	8.00	2.00	0.00	10.00		
Welder	JNM	CHRIS BRUCE	8.00	2.00	0.00	10.00		
04-0120F4	Bid Item: 078	T-L05-ESE.078	Tower Lift 0	5 Exter	nal Pair	nt Towe	er SE	
CERTIFIED CO	ATINGS COMPANY							
Labor								
Trade	Class	Name	RT Hrs C	OT Hrs I	DT Hrs	Total	Remarks	Dispute
Contractor	CERTIFIED COATING:	S COMPANY						
Contractor:	02					40.00		
Painter	JM	ALBERTO PINERA	8.00	2.00	0.00	10.00		
		ALBERTO PINERA OSCAR BERNANDEZ	8.00 8.00	2.00 2.00	0.00	10.00		
Painter	JM							

